

FIG. 1




FIG. 2




FIG. 3






FIG. 4



BLOCK DIAGRAM OF CIRCUITRY FOR MEASUREMENT OF TORQUE

FIG. 5



CIRCUIT DIAGRAM FOR MEASUREMENT OF TORQUE

FIG. 6